

## LA-UR-21-23897

Approved for public release; distribution is unlimited.

Title:

DAF Planet/Flat-Top Building: Summary of Unexpected Airborne Radioactivity on Low-Volume Air Samples Due to Ventilation Lineup

Changes

Author(s): Phelps, Eloura Danin

Intended for: Training

Issued: 2021-04-22



# NATIONAL CRITICALITY EXPERIMENTS RESEARCH CENTER NCERC




DAF Planet/Flat-Top Building: Summary of Unexpected Airborne Radioactivity on Low-Volume Air Samples Due to Ventilation Lineup Changes





## **Data Visual**









## Timeline of Supporting Information + Solutions



### **Saturday 4/10/21**

- The RCT supervisor analyzed data collected during the Planet MUSIC experiment on 3/29/21 and 3/30/21. The data indicated unexpected airborne radioactivity at the mouth of the round room. The RCT Supervisor also observed the task exhaust was running at a lower volume than normal.
- No contamination was detected on area survey swipes, no suspension limits were exceeded, and the CAM did not alarm.
- The RCT supervisor notified the DAF NOM and NCERC FOD. An administrative hold was placed on the building.

## Monday 4/12/21

- The RCT Supervisor reviewed similar data collected the week of 4/5/21 during Flat-Top operations, which also
  produces airborne radioactivity. This data indicated normal, expected results. All personnel were wearing
  respirators during both Planet MUSIC and Flat-Top operations.
- The current ventilation configuration was verified to be correct by the MSTS DAF HVAC CSE.
- A discussion with all interested stakeholders was scheduled and conducted on 4/12/21 at 1200 hrs.
- The velocity transmitter, a component that automatically adjusts air flow to maintain differential pressure, is known to be non-functional for this building. All adjustments must be performed manually.
- MSTS IH conducted an air flow test and confirmed that the building maintains sufficient pressure differential to return to normal operations.

#### **Tuesday 4/13/21**

 Subsequent discussion revealed that multiple ventilation lineup changes, which caused the anomalous condition, were conducted without notifying RadCon or secondary REOP holders of the change.

**Short Term Solution:** NOM approval is now required for any changes to ventilation lineup. Task Exhaust Fan is set at 2000 cfm (maximum setting). **Long Term Solution:** New velocity transmitters have been ordered and are expected to be installed by the end of April.